

Date: 7-11-24

Region: 4C

CSS No.: 98269

FAC ID: VA012

Maximo WO No.: 16151

Asset #:

Priority: 2



Original Work Request:

Pot feeder that was previously installed was not properly installed or setup by original contractor. It only has a high pressure line and no low pressure line to circulate properly.

Description of Repairs Needed:

Proposal is to correct pot feeder installation that was improperly installed. Investment includes shutting down the boiler, valve off, cut line and tie in piping to the pot feeder.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	8	\$ 138.00	\$ 1,104.00
Parts Runner (1)	5	\$ 95.00	\$ 475.00

Material List:

	Quantity	Cost	Total
Various Parts (see attached Quote for list)	1	\$ 550.56	\$ 550.56
Shipping & Handling	1	\$ 65.00	\$ 65.00
Misc Parts (shop supplies, unaccounted materials)	1	\$ 180.00	\$ 180.00
Trip Charge	112.5	\$ 1.75	\$ 196.88
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,579.00	\$992.44	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,571.44	\$308.57	\$154.29	\$3,034.29