

Date: 12-10-24

Region: 4C

FEMS/CSS No.: 2966013

FAC ID: VA012

Maximo WO No.: 17366

Asset #:

Priority: 2



Original Work Request:

DHW Tank Pump (Gold) not working. It was discovered on site by Casto that this pump is not working and needs to be replaced.

Description of Repairs Needed:

Troubleshoot repair needs for DHW tank pump not working.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	4	\$ 138.00	\$ 552.00
Trip Charge	1	\$ 157.50	\$ 157.50
			\$ -

Material List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

Equipment List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$709.50	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$709.50	\$85.14	\$42.57	\$837.21