

Date: 8-04-25



Region: 4C

FEMS/CSS No.: 2992617

FAC ID: VA012

Maximo WO No.: 19804

Asset #:

Priority: 2

Original Work Request:

AMSA Door #114A has been damaged beyond repair and needs replacing.

Description of Repairs Needed:

Remove and replace existing AMSA damaged door from opening. Salvage core to be used in new door, dispose of old door offsite. Door and lockset to match existing, paint door and frame to match. 5-6 week lead time on door.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	8	\$ 93.75	\$ 750.00
Travel Expense	1	\$ 283.50	\$ 283.50
			\$ -

Material List:

	Quantity	Cost	Total
F&I Exterior Door (Hollow Metal)	1	\$ 1,675.00	\$ 1,675.00
Hager Lockset	1	\$ 225.00	\$ 225.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,033.50	\$1,900.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,933.50	\$352.02	\$176.01	\$3,461.53