

Date: 9-24-25

Region: 4C

FAC ID: VA012

FEMS/CSS No.: 3220299

Maximo WO No.: 20309



Asset #:

Priority: 2

Original Work Request:

Handicap toilet flush assembly is leaking at the vacuum breaker.

Description of Repairs Needed:

Replace flush valve on handicap toilet

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	2	\$ 100.00	\$ 200.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
Sloan Flush Valve (3080053) 1.6 GPF	1	\$ 145.00	\$ 145.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$200.00	\$145.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$345.00	\$41.40	\$20.70	\$407.10