

Date: 12-12-24

Region: 4C

FEMS/CSS No.: 94501

FAC ID: VA033

Maximo WO No.: 17399

Asset #:

Priority: 3



Original Work Request:

The exterior brick to this facility needs repointed, critters are setting up residence on top of brick and mortar deterioration.

Description of Repairs Needed:

Inspect the building for areas that need repaired and what is required to repair them.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	4	\$ 83.00	\$ 332.00
Travel	1	\$ 75.00	\$ 75.00
			\$ -

Material List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

Equipment List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$407.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$407.00	\$48.84	\$24.42	\$480.26