

Date: 8-8-2024

Region: 4C

CSS No.: 94600

FAC ID: VA033

Maximo WO No.: 16382

Asset #:

Priority: 2



Original Work Request:

This facility has 4 broken windows. One has broken latches, the other 3 have broken glass. One of the broken glass is a window installed within an old window frame. All the windows need replacing.

Description of Repairs Needed:

Investigate/measure windows for replacement.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	1	\$ 300.00	\$ 300.00
Less \$194 Limit of Liability	1	\$ (194.00)	\$ (194.00)

Material List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$106.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$106.00	\$12.72	\$6.36	\$125.08