

Date: 1-30-26

Region: 4C

FAC ID: VA033

FEMS/CSS No.: 3190095

Maximo WO No.: 21200

Asset #:

Priority: 3



Original Work Request:

The spigot over the garbage grinder in the kitchen is leaking and needs to be replaced with a flexible head and sprayer spigot.

Description of Repairs Needed:

Replace existing spigot with new cartridge on sink and install sprayer and hose mounting bracket.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	2.5	\$ 100.00	\$ 250.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
Lf Cold Stem w/ HDL (T01-244725)	2	\$ 79.47	\$ 158.94
Pre-Rinse Sprayer (BOCNYRZLQH)	1	\$ 39.99	\$ 39.99
Hose w/ Spring(B-0044-H)	1	\$ 60.99	\$ 60.99
Misc (shop supplies, rags, lubricants, etc.)	1	\$ 15.00	\$ 15.00
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$250.00	\$274.92	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$524.92	\$62.99	\$31.50	\$619.41