

Date: 5-29-24

Region: 4C

FAC ID: VA039

CSS No.: 94602

Maximo WO No.: 15592

Asset #:

Priority: 2



Original Work Request:

Repair/Replace AHU that feeds the drill hall that is not working per recent PM.

Description of Repairs Needed:

Labor to investigate repairs needed for AHU feeding drill hall.

Labor:	Labor Hrs	Labor Rate	Total
Tech (1)	5	\$ 132.00	\$ 660.00
Trip Charge	1	\$ 131.25	\$ 131.25

Material List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$791.25	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$791.25	\$94.95	\$47.48	\$933.68