



Proudly serving the entire states of Virginia & North Carolina.

Altavista, VA • Charlottesville, VA • Chesapeake, VA • Christiansburg, VA  
Falmouth, VA • Lynchburg, VA • Richmond, VA • Greensboro, NC

P.O. Box 119 • Altavista, VA • 800.789.7199 • service@mooreselectric.com

Billing Address	Site Address
<b>Customer:</b> INTERNATIONAL SUPPORT GROUP <b>Address:</b> 9000 SHERIDAN ST PEMBROKE PINES FL 33024 <b>Phone:</b> 954-900-1095	<b>Customer:</b> ISG USARC VA048 RICHMOND <b>Address:</b> 1741 EAST BELT BOULEVARD RICHMOND VA 23224 <b>Phone:</b>
<b>Service Call #:</b> COM0113880	<b>Call Type:</b> COM-HVAC


Service Requested
CSS # 18242 VA048 - Repair PTAC in room 214, not working

Problems					
Description	Tech	Equip. Desc and Model	Manufacturer	Equip. Serial	Asset ID
TROUBLE SHOOT UNIT	JEREMYGRAY	PTAC ROOM 214 M# AZ65H09DABW2	General Electric	GH110115G	

Tech Notes
Site Start - 8/9/2019 12:00 PM Site Stop - 8/9/2019 2:00 PM  Arrived on site. Checked in with facilities manager. Ptac unit in room 214 space temp was 77°. Supply temp was 71°. While conducting a visual inspection I found washable filters was dirty. I cleaned off washable filters with water. Inserted them back in unit. Monitored space temp. Space temp one from 77° to 70°. Supply temp is 57°. System is operating properly at this time. Job complete.

Labor			
Date	Technician	Description	Hours
8/9/2019	JEREMIAH GRAY	REGULAR HVACR LABOR	2.00

Materials			
Date	Part Number	Description	Quantity
No records found			

<b>Signed By</b> Scott Grenier	<b>Signature</b> 	<b>Date</b> 8/9/2019
--------------------------------	--	----------------------