

**CERTIFICATION OF WORK  
SERVICE CALL**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA049

Date of Visit: 2-26-20

Contractor Personnel on Site:

1. Cory Sandlin  
2. \_\_\_\_\_  
3. \_\_\_\_\_

4. \_\_\_\_\_  
5. \_\_\_\_\_  
6. \_\_\_\_\_

**Service Call Number**

CSS# NA

WO# 11613

**Description of Repairs**

BACKFLOW ANNUAL TESTING ASSET 1414

**PLEASE VERIFY MANUFACTURER /MODEL AND SERIAL NUMBER**

Model #: 975XL      Serial #: 957661

Manufacturer: Wilkins zum

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Cory Sandlin Date: 2-26-20

Signed: Cory Sandlin

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: GS-11 MARK ANDERSON Date: 26 FEB 20

Signed: MA

E-Mail: mark.s.anderson7.mil@mail.mil



Proudly serving the entire states of Virginia & North Carolina.

Altavista, VA • Charlottesville, VA • Chesapeake, VA • Manassas, VA  
Lynchburg, VA • Richmond, VA • Raleigh, NC • Charlotte, NC

P.O. Box 119 • Altavista, VA • 800.789.7199 • service@mooreselectric.com

Billing Address	Site Address
<b>Customer:</b> TIDEWATER, INC <b>Address:</b> 6625 SELNICK DRIVE <b>Phone:</b> 614-623-9569	<b>Customer:</b> USARC VA049 CHESTERFIELD <b>Address:</b> 6700 STRATHMORE ROAD <b>Phone:</b> 6146239569
<b>Service Call #:</b> COM0126690	<b>Call Type:</b> COM-PLMB

Service Requested
WO 11613 J-1502000-29 1-pc Backflow Preventer   Feb certification
ASSET# 1414
PM# - PM-ACT-1414
02/21/20BW: EMAILED TINA TO SCHEDULE FOR 02/26 @ 9A

Problems					
Description	Tech	Equip. Desc and Model	Manufacturer	Equip. Serial	Asset ID
BACKFLOW TEST	CORYSANDLI				

Tech Notes
Tech: CORY SANDLIN, Date: 2/26/20 10:29 AM - Drove to site. Checked in at gate. Drove to building found the backflow in mechanical room. Tested backflow. Backflow passed inspection.

Labor			
Date	Technician	Description	Hours
2/26/2020	CORY SANDLIN	REGULAR PLUMBING LABOR	1.50

Materials			
Date	Part Number	Description	Quantity
2/26/2020	CMISCX-A1 INITIAL BACKFLOW	A1 INITIAL BACKFLOW TEST	1.000

Signed By	Mark	Signature		Date	2/26/2020