

## CERTIFICATION OF WORK PREVENTIVE MAINTENANCE

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA049 Date of Visit: 11-24-2020

Contractor Personnel on Site:

1. Jon Miller
2. Richard Walker
3. \_\_\_\_\_
4. \_\_\_\_\_

### Work Performed:

**Preventive Maintenance** - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO 13092 Asset 190918-247
2. \_\_\_\_\_
3. \_\_\_\_\_
4. \_\_\_\_\_
5. \_\_\_\_\_

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Richard Walker Date: 11-24-2020  
Signed: Richard Walker

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Richard Walker Date: 11-24-2020  
Signed: Richard Walker  
E-Mail: \_\_\_\_\_

Tidewater, INC  
 VA-049  
 6700 Strathmore Rd.  
 North Chesterfield VA 23237  
 (410) 540-8700

Recorded By: Jon Miller  
 (301) 580-9820  
 jmiller@bondwater.com

### Boiler Room - HVAC Equipment

Test	Hot Loop	Chill Loop		
Conductivity (as mmhos)	1765 4000 max	1265 4000 max		
pH	9.9 8 - 10.5	9.8 8 - 10.5		
Molybdate (ppm as Mo)	200 50 min	200 50 min		

#### Opening Comment

Performed scheduled service visit.

#### Hot Water Loop

Online 

All readings indicate good levels of protection for closed system. Corrosion inhibitor residual is excellent at this time.

#### Chill Water Loop

Offline 

All readings indicate good levels of protection for closed system. Corrosion inhibitor residual is excellent at this time. Chill Loop is Offline