

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

OTHER RECURRING SERVICES CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA-049 Date of Visit: 8/17/20

Contractor Personnel on Site:

- | | |
|----------------------|----------|
| 1. <u>Jon Miller</u> | 4. _____ |
| 2. _____ | 5. _____ |
| 3. _____ | 6. _____ |

Work Performed: HVAC Water Treatment Service


Other Recurring Services

- | |
|---------------------------------------|
| 1. <u>100 12563 ASSET 190918 -247</u> |
| 2. _____ |
| 3. _____ |
| 4. _____ |

CERTIFICATION OF WORK

To be signed by the Contractor:


Print Name: Jon Miller Date: 8/17/20

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Martin S. Rhoades Jr / SFC Date: 17 Aug 2020

Signed: 

E-Mail: Martin.S.Rhoades4.mil@mail.mil

Tidewater, INC
VA-049
6700 Strathmore Rd.
North Chesterfield VA 23237
(410) 540-8700

Recorded By: Jon Miller
(301) 580-9820
jmiller@bondwater.com

Boiler Room - HVAC Equipment

Test	Hot Loop	Chill Loop		
Conductivity (as mmhos)	1652 4000 max	1305 4000 max		
pH	9.9 8 - 10.5	9.8 8 - 10.5		
Molybdate (ppm as Mo)	200 50 min	195 50 min		

Opening Comment

Performed quarterly scheduled service visit.

Hot Water Loop

Offline 

All readings indicate good levels of protection for closed system. Corrosion inhibitor residual is excellent at this time. Hot Loop is Offline

Chill Water Loop

Online 

All readings indicate good levels of protection for closed system. Corrosion inhibitor residual is excellent at this time.