

Tidewater, INC
VA-049
6700 Strathmore Rd.
North Chesterfield VA 23237
(410) 540-8700

Recorded By: Jon Miller
(301) 580-9820
jmillier@bondwater.com

Boiler Room - HVAC Equipment

Test	Hot Loop	Chill Loop		
Conductivity (as mmhos)	1100 4000 max	692 4000 max		
pH	9.6 8 - 10.5	10.1 8 - 10.5		
Molybdate (ppm as Mo)	200 50 min	160 50 min		

Opening Comment

Performed scheduled service visit.

Hot Water LoopOnline 

All readings indicate good levels of protection for closed system. Corrosion inhibitor residual is excellent at this time. Replaced filter in filter housing.

Chill Water LoopOnline 

All readings indicate good levels of protection for closed system. Corrosion inhibitor residual is excellent at this time. Replaced filter in filter housing.