



Proudly serving the entire states of Virginia & North Carolina.

Altavista, VA • Charlottesville, VA • Chesapeake, VA • Christiansburg, VA  
Falmouth, VA • Lynchburg, VA • Richmond, VA • Greensboro, NC

P.O. Box 119 • Altavista, VA • 800.789.7199 • service@mooreselectric.com

Billing Address		Site Address	
Customer:	INTERNATIONAL SUPPORT GROUP	Customer:	ISA USARC VA049 CHESTERFIELD
Address:	9000 SHERIDAN ST PEMBROKE PINES FL 33024	Address:	6700 STRATHMORE ROAD NORTH CHESTERFIELD VA 23237
Phone:	954-900-1095	Phone:	8045855211
Service Call #:	COM0104133	Call Type:	COM-PLMB

#### Service Requested

CSS-15477 QUOTE APPROVAL 2037.72 / 14 HRS

##### DESCRIPTION OF EQUIPMENT:

"Sink Drains

"

##### DESCRIPTION OF REPAIRS:

"Moore's is proposing to cut into the wall located in the men's restrooms where back to back sinks are clogged. Will remove tile and open up wall to gain access to the pipe in wall. Will cut out a 20" x 20" hole to allow access and working space. Will cut out a section of the clogged pipe, install a tee wye, cut out section and cleanout. This will make it so the drain can be snaked in the future, should any issues arise. Once the pipe is cut and tee installed, will snake drain and clear out sinks so that they are able to drain. Will then ensure proper operation.

\*\*Please note: This is not guaranteed to permanently solve the issue, but this will need to be done in order to further diagnose issue at the least. \*\*\*

#### Problems

Description	Tech	Equip. Desc and Model	Manufacturer	Equip. Serial	Asset ID
QUOTED WORK	CORYSANDLI				

#### Tech Notes

4/11/19 Drove to site. Checked in at main gate. Had to wait an hour for the front office to let me in the facility to work. Got to facility. Started cutting out wall in women's room to gain access behind wall to see how to repair drain. Had to go to supply house to get a chisel for hammer drill to finish chipping wall. Cut a 14x14 hole under women's room vanity to gain access to piping. Got material list to fix the drain. Went to supply house to get materials for job. Arrived back from supply house. Took apart drain inside wall. Found the drain clogged from the connection at the cross drain to the entrance of the main drain, which is about 2'. Removed cross and drain 45's. Stuck a drain king down line to clear drain to the main in the floor. Had to leave early. Packed things up and left. Will come back to finish job next day.

4/12/19 Went to supply house to get access panel for wall. Drove to site. Checked in at main office. Office would not allow me onsite to work at first. Made a couple of phone calls. Was allowed to come on site for the day to finish the job. Will have to get a sponsor for any further work that has to be done on base. Gained access to building. Ran new drain line from floor connection at to both men's and women's sink drains. Ran new pvc vent to existing 90 above. Installed new trap adaptors. Installed new access panel under vanity in women's room. Installed a cleanout tee under cross drain to be able to snake line in either direction. Tested new drain. Drains are draining fine at this time. Cleaned up debris and put tools in van.

#### Labor

Date	Technician	Description	Hours
4/11/2019	CORY SANDLIN	REGULAR PLUMBING LABOR	4.50
4/11/2019	CORY SANDLIN	REGULAR PLUMBING LABOR	3.00
4/12/2019	CORY SANDLIN	REGULAR PLUMBING LABOR	6.00

#### Materials

Date	Part Number	Description	Quantity
4/3/2019	CMISCX-NON-STOCK ITEM	MATERIALS	1.000
4/11/2019	CMISCX-NON-STOCK ITEM	Items for PO 190008	1.000
4/12/2019	CMISCX-NON-STOCK ITEM	Items for PO 190060	1.000

Signed By	Sean milessean mi	Signature		Date	4/12/2019
-----------	-------------------	-----------	--	------	-----------

CERTIFICATION OF WORK  
(To be completed by the Contractor and saved in the Contractor's CMMS)FACID/Building: VADY9Date of Visit: 4-11-19/4-12-19

Contractor Personnel on Site:

1. Cory Sandlin

2. \_\_\_\_\_

## Work Performed:

**Preventive Maintenance** - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO# \_\_\_\_\_

## Service Calls – Service Call Number and Description

1. CSS# 15477 - cut wall Repair/Replace drains so men's and  
~~women's~~ sinks will drain.

3. CSS# \_\_\_\_\_

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Cory Sandlin Date: 4-12-19  
Signed: Cory Sandlin

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

On behalf of Mr. Chris Lange  
Print Name/Rank: Sean W. Miles/CIV Date: 2019/04/12  
Signed: Sean W. Miles  
E-Mail: Sean.W.Miles4.civ@mail.mil





IN U.S.A. 10/21/18 05:03

ET. #15 JOE'S

