

## Additional Funding Request

<b>Site: VA049</b>	<b>WO# 6450      CSS # 15477      Asset# NA</b>
Description of Repairs	Sinks in the male and female handicap bathrooms are clogged
Diagnosis: Initial Work Order <b>CSS# 15477</b>	Snake drain lines
Explanation of Additional Costs for Repairs	Labor and material to properly snake the drains
Additional Labor Cost to Perform Repairs	\$ 5x120.00- \$600
Additional Material Cost to Perform Repairs	Truck Fee- \$55.00 Fittings/piping- \$19.08
Total Cost of Repair	\$674.08



P.O. Box 119 • Altavista, VA 24517 • 24 Hour Service: 800.789.7199 • Fax: 888.722.2712 • MooresElectric.com

## Proposal

October 3, 2018

Quotes are valid for 30 days.

International Support Group  
6700 Strathmore Rd.  
North Chesterfield, VA 23237  
Email [tcraig@internationalsupportgroup.com](mailto:tcraig@internationalsupportgroup.com)

Contact Name Troy Craig  
Telephone 804-585-5211  
Cell Phone 954-900-1095  
Fax Number 0.00

### DESCRIPTION OF EQUIPMENT:

Restroom Drain line

### DESCRIPTION OF REPAIRS:

Moore's will locate vent in ceiling for men's and women's hallway restroom in order to be able to drill snake the drains through the vent. Once the vent is found, will cut out piece of piping and snake drain in order to clear the drain. Pipe will be replaced in line to connect the vent.

### MATERIAL, EQUIP OR PARTS

Fitting/piping  
Truck Fee

Quantity	Sell price
1.00	\$ 19.08
1.00	\$ 55.00
<b>Material Total</b>	<b>\$ 74.08</b>

### LABOR ITEMIZED

Labor - One Man Proposed 5

	Labor
\$ 120.00	\$ 600.00
<b>Labor Total</b>	<b>\$ 900.00</b>

Thank you for your business. If you have any questions or concerns,  
please feel free to contact us via telephone or [quotes@mooreselectric.com](mailto:quotes@mooreselectric.com)

<b>Materials</b>	<b>\$ 74.08</b>
<b>Labor</b>	<b>\$ 900.00</b>
<b>TOTAL</b>	<b>\$ 974.08</b>

*This includes  
original call cost.*

Robert Lowery, Changeout Estimator 434-309-2591  
Amy Hockaday, Estimator 434-309-2569  
James Davis, Estimator 434-309-2568  
Adam Barker, Estimator 434-369-3514  
Jared Underwood, Estimator 434-306-2446

Approved by: \_\_\_\_\_

#### Standard Terms and Conditions

Payments past 30 days are subject to 1.5% monthly service charge on unpaid balance. Additional charges for payments made through credit cards may apply. Late payments sent to collections or legal process the purchaser agrees to pay all costs, expenses, and reasonable attorney fees.



**CERTIFICATION OF WORK**  
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA049 Date of Visit: 10-1-18  
Contractor Personnel on Site:

1. Cory Sandlin 2. \_\_\_\_\_

**Work Performed:**

**Preventive Maintenance - Services Completed** (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO# COM0092661

**Service Calls - Service Call Number and Description**

1. CSS# \_\_\_\_\_
2. CSS# \_\_\_\_\_
3. CSS# \_\_\_\_\_

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Cory Sandlin Date: 10-1-18

Signed: Cory Sandlin

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Jeff Constantine Date: 10-1-18

Signed: Jeff Constantine

E-Mail: jeffrey.a.constantine.civ@mail.mil