

CERTIFICATION OF WORK
SERVICE CALL

COM0126694

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA099 Date of Visit: 2-25-2020

Contractor Personnel on Site:

1. Benny Heater
2. _____
3. _____
4. _____
5. _____
6. _____

Service Call Number

CSS# NA WO# 11616

Description of Repairs

BACKFLOW ANNUAL TESTING ASSET 1442

Test Pass

PLEASE VERIFY MANUFACTURER /MODEL AND SERIAL NUMBER

MANUFAT? MODEL 975XL SER 3696104

Wilkins

3/4

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Benny Heater Date: 2-25-2020

Signed: Benny Heater

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Donald L. Huson Date: 2-25-2020

Signed: Donald L. Huson

E-Mail: Donald.L.Huson.CTR@mail.mil



Proudly serving the entire states of Virginia & North Carolina.

Altavista, VA • Charlottesville, VA • Chesapeake, VA • Manassas, VA
Lynchburg, VA • Richmond, VA • Raleigh, NC • Charlotte, NC

P.O. Box 119 • Altavista, VA • 800.789.7199 • service@mooreselectric.com

Billing Address	Site Address
Customer: TIDEWATER, INC Address: 6625 SELNICK DRIVE Phone: ELKRIDGE MD 21075 614-623-9569	Customer: USARC VA099 BEDFORD Address: 1117 HARMONY LANE Phone: BEDFORD VA 24523 6146239569
Service Call #: COM0126694	Call Type: COM-PLMB

Service Requested

WO 11616 J-1502000-29 1-pc Backflow Preventer 2in | Feb certification

MODEL - 975XL SERIAL - 3696104

ASSET # 1442
PM # PM-ACT-1442

02/21/20BW: EMAILED TINA TO SCHEDULE FOR 02/25 @ 9A

Problems

Description	Tech	Equip. Desc and Model	Manufacturer	Equip. Serial	Asset ID
BACKFLOW TEST	BENNYHEATE		PLUMBING OR ELECTRICAL EQUIPMENT		

Tech Notes

Tech: BENNY HEATER, Date: 2/25/20 11:30 AM - Test ASSET 1442 backflow . Pass . Fill out paper work and got work order sign. Took pictures

Labor

Date	Technician	Description	Hours
2/25/2020	BENNY HEATER	REGULAR PLUMBING LABOR	1.50

Materials

Date	Part Number	Description	Quantity
2/25/2020	CMISCX-A1 INITIAL BACKFLOW	A1 INITIAL BACKFLOW TEST	1.500

Signed By		Signature		Date	