

Tidewater, INC
VA-099
1117 Harmony Dr.
Bedford VA 24523
(410) 540-8700

Recorded By: Jon Miller
(301) 580-9820
jmillier@bondwater.com

Mechanical Room - HVAC Equipment

Test	Hot Loop	Chill Loop		
Conductivity (as mmhos)	3492 4000 max	3323 4000 max		
pH	8.1 8 - 10.5	10.0 8 - 10.5		
Molybdate (ppm as Mo)	200 50 min	50 50 min		

Opening Comment

Performed monthly scheduled service visit.

Hot Water LoopOnline 

All readings indicate good levels of protection for closed system. Corrosion inhibitor residual is excellent at this time. Replaced filter in filter housing.

Chill Water LoopOffline 

All readings indicate good levels of protection for closed system. Corrosion inhibitor residual is excellent at this time. Chill Loop is Offline