

Tidewater, INC
 VA-099
 1117 Harmony Dr.
 Bedford VA 24523
 (410) 540-8700

Recorded By: Jon Miller
 (301) 580-9820
 jmiller@bondwater.com

2nd Floor Mechanical Room - HVAC Equipment

Test	Hot Loop	Chill Loop		
Conductivity (as mmhos)	3178 4000 max	3842 4000 max		
pH	8.9 8 - 10.5	9.9 8 - 10.5		
Molybdate (ppm as Mo)	60 50 min	50 50 min		

Opening Comment

Performed monthly scheduled service visit.

Hot Water Loop

Online 

All readings indicate good levels of protection for closed system. Corrosion inhibitor residual is excellent at this time.

Chill Water Loop

Online 

All readings indicate good levels of protection for closed system. Corrosion inhibitor residual is excellent at this time.