

Tidewater, INC
VA-099
1117 Harmony Dr.
Bedford VA 24523
(410) 540-8700

Recorded By: Jon Miller
(301) 580-9820
jmillier@bondwater.com

Mechanical Room - HVAC Equipment

Test	Hot Loop	Chill Loop		
Conductivity (as mmhos)	3477 4000 max	3327 4000 max		
pH	8.3 8 - 10.5	10.0 8 - 10.5		
Molybdate (ppm as Mo)	80 50 min	65 50 min		

Opening Comment

Performed monthly scheduled service visit.

Hot Water Loop**Online**

All readings indicate good levels of protection for closed system. Corrosion inhibitor residual is excellent at this time. Installed filter in filter housing.

Chill Water Loop**Online**

All readings indicate good levels of protection for closed system. Corrosion inhibitor residual is excellent at this time. Installed filter in filter housing.