



---

**CERTIFICATE OF BOILER  
OR PRESSURE VESSEL INSPECTION**

Boiler or Vessel No.:	2357	State or Standard No.:	2357
-----------------------	------	------------------------	------

This is to certify that the here in-described boiler/pressure vessel inspected by

ARISE

on: 10/29/2018		
may be operated at a pressure not to exceed	160	pounds per square inch.

<b>Name of User</b>	US Army Reserve Region 4 Zone C9-VA099				
<b>Address</b>	1117 Harmony Ln Bedford, VA 24523				
<b>Location</b>	boiler room				
<b>Type</b>	Water Tube	<b>Manufacturer</b>	Lochinvar	<b>Date Mfg.</b>	

**Certificate expires 10/29/2020 or upon the cancellation of the company's insurance  
coverage on the object, whichever occurs first.**

**INSPECTIONS**

TYPE OF INSPECTION	DATE	INSPECTOR	COMMISSION NUMBER
External	10/29/2018	Henry Best	NonJ2655

This document should be posted in a conspicuous place, accessible to concerned individuals and  
located in the general area of the boiler or pressure vessel.



---

**CERTIFICATE OF BOILER  
OR PRESSURE VESSEL INSPECTION**

Boiler or Vessel No.:	236336	State or Standard No.:	2358
-----------------------	--------	------------------------	------

This is to certify that the here in-described boiler/pressure vessel inspected by

ARISE

on: 10/29/2018		
may be operated at a pressure not to exceed	160	pounds per square inch.

<b>Name of User</b>	US Army Reserve Region 4 Zone C9-VA099				
<b>Address</b>	1117 Harmony Ln Bedford, VA 24523				
<b>Location</b>	Boiler room				
<b>Type</b>	Water Tube	<b>Manufacturer</b>	Lochinvar	<b>Date Mfg.</b>	

**Certificate expires 10/29/2020 or upon the cancellation of the company's insurance  
coverage on the object, whichever occurs first.**

**INSPECTIONS**

TYPE OF INSPECTION	DATE	INSPECTOR	COMMISSION NUMBER
External	10/29/2018	Henry Best	NonJ2655

This document should be posted in a conspicuous place, accessible to concerned individuals and  
located in the general area of the boiler or pressure vessel.



---

**CERTIFICATE OF BOILER  
OR PRESSURE VESSEL INSPECTION**

Boiler or Vessel No.:	234409	State or Standard No.:	2359
-----------------------	--------	------------------------	------

This is to certify that the here in-described boiler/pressure vessel inspected by

ARISE

on: 10/29/2018		
may be operated at a pressure not to exceed	160	pounds per square inch.

<b>Name of User</b>	US Army Reserve Region 4 Zone C9-VA099				
<b>Address</b>	1117 Harmony Ln Bedford, VA 24523				
<b>Location</b>	Boiler room				
<b>Type</b>	Water Tube	<b>Manufacturer</b>	Lochinvar	<b>Date Mfg.</b>	

**Certificate expires 10/29/2020 or upon the cancellation of the company's insurance  
coverage on the object, whichever occurs first.**

**INSPECTIONS**

TYPE OF INSPECTION	DATE	INSPECTOR	COMMISSION NUMBER
External	10/29/2018	Henry Best	NonJ2655

This document should be posted in a conspicuous place, accessible to concerned individuals and  
located in the general area of the boiler or pressure vessel.





---

**CERTIFICATE OF BOILER  
OR PRESSURE VESSEL INSPECTION**

Boiler or Vessel No.:	234406	State or Standard No.:	2360
-----------------------	--------	------------------------	------

This is to certify that the here in-described boiler/pressure vessel inspected by

ARISE

on: 10/29/2018		
may be operated at a pressure not to exceed	160	pounds per square inch.

<b>Name of User</b>	US Army Reserve Region 4 Zone C9-VA099				
<b>Address</b>	1117 Harmony Ln Bedford, VA 24523				
<b>Location</b>	Boiler room				
<b>Type</b>	Water Tube	<b>Manufacturer</b>	Lochinvar	<b>Date Mfg.</b>	

**Certificate expires 10/29/2020 or upon the cancellation of the company's insurance  
coverage on the object, whichever occurs first.**

**INSPECTIONS**

TYPE OF INSPECTION	DATE	INSPECTOR	COMMISSION NUMBER
External	10/29/2018	Henry Best	NonJ2655

This document should be posted in a conspicuous place, accessible to concerned individuals and  
located in the general area of the boiler or pressure vessel.



Grand Bay I  
7000 South Edgerton Suite 100  
Brecksville, OH 44141-3172  
Phone: (440) 740-0197  
FAX: (440) 746-8957  
www.ariseinc.com

October 30, 2018

Mr. Brian Leighton (e-mail)  
Senior Site Supervisor  
US ARMY RESERVE – REGION 4 ZONE C9  
International Support Group  
9000 Sheridan Street Suite 172  
Pembroke Pines, FL 33024-8803  
[bleighton@internationalsupportgroup.com](mailto:bleighton@internationalsupportgroup.com)

RE: **Non-Jurisdictional Inspection**  
US Army Reserve Region 4 Zone C9  
Location No. VA099  
1117 Harmony Lane  
Bedford, VA 24523  
File No. 6082.0019

Dear Mr. Leighton:

A Non-Jurisdictional Inspection was performed at the captioned location on October 29, 2018, in the company of Troy Craig, for the purpose of issuing ARISE Certificates of Inspection. The following objects were inspected:

Manufacturer	Type of Object	Object No.	NB No.	Type of Insp.
Lochinvar	Water Tube	2357	2357	External Cert
Lochinvar	Water Tube	2358	236336	External Cert
Lochinvar	Water Tube	2359	234409	External Cert
Lochinvar	Water Tube	2360	234406	External Cert

No violations or recommendations have been issued as a result of this inspection.

I would like to thank you, and those members of your staff present, for your cooperation and assistance. If you should have any questions or comments regarding this inspection, please contact our Brecksville office at (440) 740-0197.

Regards,

*Hank Best/pm*

Hank Best  
B & M Consultant

HB:pm  
Enc.  
cc: File copy

---

YOUR CONTINUING EFFORT IS ESSENTIAL TO ACCIDENT PREVENTION, COMPLIANCE WITH OSHA AND ALL OTHER SAFETY LEGISLATION. OUR ASSISTANCE MAY BE USED AS AN ADJUNCT IN CERTAIN AREAS OF THAT EFFORT, BUT WE ASSUME AND HAVE NO RESPONSIBILITY TO YOU OR OTHERS FOR THE CONTROL OR CORRECTION OF CONDITIONS OR PRACTICES EXISTING AT YOUR PREMISES WHETHER OR NOT LISTED IN THIS REPORT. FURTHER, WE DO NOT WARRANT THAT THE COMPLETION OF ANY RECOMMENDATIONS IN THIS REPORT WILL ASSURE THAT THE PREMISES OR OPERATIONS ARE SAFE OR HEALTHFUL, OR ARE IN COMPLIANCE WITH ANY LAW, RULE, OR REGULATION.