

## Additional Funding Request

<b>Site: VA099</b>	<b>WO# 8024</b>	<b>CSS # 18192</b>	<b>Asset# NA</b>
Description of Repairs	Backflow repairs		
Diagnosis: Initial Work Order <b>CSS# 18192</b>	Backflow repairs		
Explanation of Additional Costs for Repairs	Labor and material to repair backflow		
Additional Labor Cost to Perform Repairs	$8 \times \$120.00 = \$960.00$		
Additional Material Cost to Perform Repairs	\$300.40		
Total Cost of Repair	\$1,260.40 - \$250 (CM credit) = \$1,010.40		



P.O. Box 119 • Altavista, VA 24517 • 24 Hour Service: 800.789.7199 • Fax: 888.722.2712 • MooresElectric.com

## Proposal

March 7, 2019

Quotes are valid for 30 days.

USARC VA099 Bedford 1117 Harmony Lane Bedford, VA 24523 Email	Contact Name Telephone Cell Phone Fax Number	George Grant 304-663-8670 0.00
	<a href="mailto:ggrant@internationalsupportgroup.com">ggrant@internationalsupportgroup.com</a>	
	<a href="mailto:jmerchant@internationalsupportgroup.com">jmerchant@internationalsupportgroup.com</a>	

### DESCRIPTION OF EQUIPMENT:

BOILER BACKFLOW DEVICE

### DESCRIPTION OF REPAIRS:

The boiler backflow at the site listed above failed test and needs to be disassembled, cleaned, and rebuilt. Moore's is proposing to disassemble, clean, and rebuild #1 and #2 relief valves. We will retest to certify the backflow and send test report into the Bedford Water Dept. We will install PVC air gap drain over to floor drain and secure it to the wall and floor. Clean area after work and fill out all paper work.

### MATERIAL, EQUIP OR PARTS

	Quantity	Sell price
3/4 Complete Backflow Preventer Repair Kit	1.00	\$ 122.84
1" x 20' PVC SCH 40 BE Pipe	40.00	\$ 15.84
1" SXS PVC SCH 40 90 ELL	6.00	\$ 3.10
1" GALV Pipe Strap	6.00	\$ 1.44
2" PVC-DWV CPLG	1.00	\$ 0.88
2" X 1" SPGXS PVC SCH 40 Bushing	1.00	\$ 1.19
1" GALV Split Ring Hanger	2.00	\$ 2.76
Retest Fee	1.00	\$ 85.00
Material Tax	1.00	\$ 12.35
Truck Fee	1.00	\$ 55.00
<b>Material Total</b>	\$ 300.40	

### LABOR ITEMIZED

		Labor
Labor - One Man Incurred	0	\$ 120.00 \$ -
Labor - One Man	8	\$ 120.00 \$ 960.00
Labor - Second Man	0	\$ 120.00 \$ -
<b>Labor Total</b>		<b>\$ 960.00</b>

Thank you for your business. If you have any questions or concerns, please feel free to contact us via telephone or [quotes@mooreselectric.com](mailto:quotes@mooreselectric.com)

<b>Materials</b>	\$ 300.40
<b>Labor</b>	\$ 960.00
<b>TOTAL</b>	<b>\$ 1,260.40</b>

Robert Lowery, Changeout Estimator 434-309-2591  
Amy Hockaday, Estimator 434-309-2569  
James Davis, Estimator 434-309-2568  
Adam Barker, Estimator 434-369-3514  
Jared Underwood, Estimator 434-306-2446

Approved by: \_\_\_\_\_

#### Standard Terms and Conditions

Payments past 30 days are subject to 1.5% monthly service charge on unpaid balance. Additional charges for payments made through credit cards may apply. Late payments sent to collections or legal process the purchaser agrees to pay all costs, expenses, and reasonable attorney fees.



The Family Advantage

Plumbing • Well • Septic Supply



## Quotation

QUOTE TO:

MOORES ELECTRICAL & MECH  
CONST INC  
101 EDGEWOOD AVENUE  
PO BOX 119  
ALTAVISTA, VA 24517

SHIP TO:

MOORES ELECTRICAL & MECH  
CONST INC  
101 EDGEWOOD AVENUE  
PO BOX 119  
ALTAVISTA, VA 24517

EXPIRATION DATE	QUOTE NUMBER
04/13/2019	S5002399
PAGE NO.	
	1 of 1

CUSTOMER NUMBER		CUSTOMER PO NUMBER	JOB NAME / RELEASE NUMBER	
WRITER		SHIP VIA	TERMS	SHIP DATE
ORDER QTY	DESCRIPTION	UNIT PRICE	EXT PRICE	
1ea	4A00410 3/4" COMPLETE BACKFLOW PREVENTER INTERNAL REPAIR KIT APOLLO *** Above not returnable ini ____ ** Pn: 229588	102.370/ea	102.37	
40ft	33914BE 1" X 20' PVC SCH 40 BE PIPE Pn: 8339	0.330/ft	13.20	
6ea	406-010 1" SXS PVC SCH 40 90 ELL Pn: 25919	0.430/ea	2.58	
6ea	600-1 1" GALV PIPE STRAP 100053 Pn: 6822	0.200/ea	1.20	
1ea	P100-2 2" PVC-DWV CPLG Pn: 1254	0.730/ea	0.73	
1ea	437-249 2" X 1" SPGXS PVC SCH 40 BUSHING Pn: 15409	0.990/ea	0.99	
2ea	385-1 1" GALV SPLIT RING HANGER 508R3100EG Pn: 3748	1.150/ea	2.30	
		Subtotal	123.37	
		Frieght Charges	15.95	
		Handling Charges	0.00	
		Estimated Tax	6.54	
		Amount Due	145.86	