

Additional Funding Request

Site: VA099	WO# 9577 CSS # 19447 Asset# NA
Description of Repairs	Need to replace burner tube
Diagnosis: Initial Work Order CSS# 19447	There is a crack in the baffle in the lower half of the combustion chamber
Explanation of Additional Costs for Repairs	Labor and material to replace burner tube
Additional Labor Cost to Perform Repairs	5 x \$120.00= \$600.00
Additional Material Cost to Perform Repairs	\$1,013.96
Total Cost of Repair	\$1,613.96



P.O. Box 119 • Altavista, VA 24517 • 24 Hour Service: 800.789.7199 • Fax: 888.722.2712 • MooresElectric.com

Proposal

July 22, 2019

Quotes are valid for 30 days.

USARC VA099
1117 Harmony Lane
Bedford VA 24523
Email

ggrant@internationalsupportgroup.com
jmerchant@internationalsupportgroup.com

Contact Name George Grant
Telephone 304-663-8670
Cell Phone
Fax Number

DESCRIPTION OF EQUIPMENT:

Unit #: HWB-2
Area Unit Serves*: FACILITY HEAT
Make: LOCHINVAR Model: KBN-400 Serial #: K12H10234406

DESCRIPTION OF PROBLEM:

While performing planned maintenance on the boilers on site, Moore's technician Howard Floyd found that the burner tube for Hot water Boiler 2 has a crack in it and requires replacing.

DESCRIPTION OF REPAIRS:

Moore's is proposing to have our technician return to site in order to replace the burner tube for HWB-2. Tech will remove the cracked tube and install new one. Once new tube is installed, will start, test, and ensure proper operation.

MATERIAL, EQUIP OR PARTS

Burner Tube Assembly
Material Tax
Truck Fee

Quantity	Sell price
1.00	\$ 910.69
1.00	\$ 48.27
1.00	\$ 55.00
Material Total	\$ 1,013.96

LABOR ITEMIZED

Labor - One Man 5

	Labor
\$ 120.00	\$ 600.00
Labor Total	\$ 600.00

Thank you for your business. If you have any questions or concerns, please feel free to contact us via telephone or quotes@mooreselectric.com

Materials	\$ 1,013.96
Labor	\$ 600.00
TOTAL	\$ 1,613.96

*This does NOT include
original call cost.*

Robert Lowery, Changeout Estimator 434-309-2591
Amy Hockaday, Estimator 434-309-2569
James Davis, Estimator 434-309-2568
Adam Barker, Estimator 434-369-3514
Jared Underwood, Estimator 434-306-2446

Approved by: _____

Standard Terms and Conditions

Payments past 30 days are subject to 1.5% monthly service charge on unpaid balance. Additional charges for payments made through credit cards may apply. Late payments sent to collections or legal process the purchaser agrees to pay all costs, expenses, and reasonable attorney fees.

QUOTATION

Southern Refrigeration Corporation
1620 Wythe Rd.
Lynchburg, VA 24501
434-846-6028

Order Number	
1655151	
Order Date	Page
4/30/2019 10:39:51	1 of 1

Quote Expires On 5/30/2019

Bill To:

MOORE'S ELECTRIC
PO BOX 119
ALTAVISTA , VA 24517
US

Ship To:

MOORE'S ELECTRIC
101 EDGEWOOD AVE
ALTAVISTA , VA 24517
US

Requested By: JARED UNDERWOOD

Customer ID: 13336

<i>PO Number</i>					<i>Taker</i>				
BEDFORD ARMY RESERVE					MMOORE				
<i>Quantities</i>					<i>Item ID</i>	<i>Pricing</i>	<i>Unit</i>	<i>Extended</i>	
<i>Ordered</i>	<i>Allocated</i>	<i>Remaining</i>	<i>UOM</i>	<i>Disp.</i>	<i>Item Description</i>	<i>UOM</i>	<i>Price</i>	<i>Price</i>	

PLUS FREIGHT

1	0	1	EA		100135311 LOCHINVAR BURNER ASSY W/ GASKE BURNER ASSY W/ GASKET	EA	758.91	758.91	
---	---	---	----	--	--	----	--------	--------	--

Total Lines: 1

SUB-TOTAL: 758.91

TAX: 40.22

AMOUNT DUE: 799.13

U.S. Dollars

