

**CERTIFICATION OF WORK
PREVENTIVE MAINTENANCE**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: _____ Date of Visit: _____

Contractor Personnel on Site:

- | | |
|----------|----------|
| 1. _____ | 3. _____ |
| 2. _____ | 4. _____ |

Work Performed:


Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. _____
2. _____
3. _____
4. _____
5. _____

CERTIFICATION OF WORK

To be signed by the Contractor:


Print Name: _____ Date: _____

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: _____ Date: _____

Signed: 

E-Mail: _____

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

SITE AND BLDG #: VA006-01

**MECHANIC
SIGNATURE:**


DATE: 11-5-19

LOCATION/RM #: **WO# 11120**

START TIME: 7 AM


FINISH TIME: 5:30 PM

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	
TO BE PERFORMED AT EACH INSPECTION SERVICE				
1	Check, clean, and/or replace filters as required.	<input checked="" type="checkbox"/>		
2	Initial and Date Filter (if disposable)	<input checked="" type="checkbox"/>		
3	Initial and Date Yellow Maintenance Tag (if applicable)	<input checked="" type="checkbox"/>		
ASSET #	SIZE	QTY		NOTES/ ACTIONS
	Record Size :			
22389	16X20X2 / 16X25X2	4 / 2		
22398	20X20X	1		ASSET # 2239
				↓




Assembly Hall
CIEJNB Air HANDLER.
HEAT only HOT WATER coil
NEEDS To BE ADDED To PMS

outside air -Filter gets replaced annually But inspect



ASSET 2238
IS A HEAT PUMP
SPRIT SYSTEM
←



Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Technician

Additional Notes: