

## CERTIFICATION OF WORK SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: VA050

Date of Visit: 2-26-20

Contractor Personnel on Site:

- |                        |          |
|------------------------|----------|
| 1. <u>Cory Sandlin</u> | 4. _____ |
| 2. _____               | 5. _____ |
| 3. _____               | 6. _____ |

Service Call Number

CSS# NA WO# 11614

### Description of Repairs

BACKFLOW ANNUAL TESTING ASSET 1419

**PLEASE VERIFY MANUFACTURER /MODEL AND SERIAL NUMBER**

Manufacturer? ~~Model 709MOD Serial 365248~~ 3/4"

Manufacturers: Wilkins zurn / Model #: 975XL / Serial #: 4607038

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Cory Sandlin Date: 2-26-20

Signed: Cory Sandlin

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Thessolonia M. Friend Date: 2/26/20

Signed: [Signature]

E-Mail: thessolonia.m.friend.mil@mail.mil





Proudly serving the entire states of Virginia & North Carolina.

Altavista, VA • Charlottesville, VA • Chesapeake, VA • Manassas, VA  
Lynchburg, VA • Richmond, VA • Raleigh, NC • Charlotte, NC

P.O. Box 119 • Altavista, VA • 800.789.7199 • service@mooreselectric.com

Billing Address	Site Address
<b>Customer:</b> TIDEWATER, INC <b>Address:</b> 6625 SELNICK DRIVE ELKRIDGE MD 21075 <b>Phone:</b> 614-623-9569	<b>Customer:</b> USARC VA050 N CHESTERFIELD <b>Address:</b> 6002 STRATHMORE ROAD NORTH CHESTERFIELD VA 23232 <b>Phone:</b> 6146239569
<b>Service Call #:</b> COM0126692	<b>Call Type:</b> COM-PLMB


Service Requested
WO 11614 J-1502000-29 1-pc Backflow Preventer 3/4in   Feb certification  MODEL - 709MOD SERIAL - 365215  PM-ACT-1419  02/21/20BW: EMAILED TINA TO SCHEUDLE FOR 02/26 @ 9A

Problems					
Description	Tech	Equip. Desc and Model	Manufacturer	Equip. Serial	Asset ID
BACKFLOW TEST	CORYSANDLI				

Tech Notes
Tech: CORY SANDLIN, Date: 2/26/20 11:14 AM - Drove to site. Checked in with mod. Manager took me to boiler room to test backflow. Tested back flow. Backflow passed inspection.

Labor			
Date	Technician	Description	Hours
2/26/2020	CORY SANDLIN	COMMERCIAL TRAVEL TIME	0.25
2/26/2020	CORY SANDLIN	REGULAR PLUMBING LABOR	1.00

Materials			
Date	Part Number	Description	Quantity
No records found			

<b>Signed By</b> On wo	<b>Signature</b> 	<b>Date</b> 2/26/2020
------------------------	---	-----------------------