



## Service Items

Name	Description	Tier 1 Price	Unit Type	QTY	Taxable
Labor	See attached pages for details of work performed.	\$0.00	Hour	1	N

**TOTAL\*:** **\$0.00**

\* Not including taxes



## Service Forms

**Daily Form** Fill out every day. even on PMs, and projects

**TECH NAME** Tom Timlin

**DATE** 5/9/23

**POINT OF CONTACT:** Scott

**DESCRIPTION OF WORK PERFORMED** Performed the Compressor PM on the Garage compressor. Drained water from the tank, changed both oil filters, Air filter, and changed the oil. Reset the maintenance timers. The compressor is running good at this time.

**TOOLS USED** hand tools

**MATERIALS USED OR PICTURE OF TAG\*** Parts ordered by Ryan

**HOURS** REGULAR:  
OVERTIME:

**Air compressor pm** Air compressor pm form

**Manufacturer** Gardner Denver

**Unit location / Tag** boiler room on main building

**Model / Serial Number** Camera 05/09/2023 12:00  
PM.jpg



**Belts** 3: ZS1059044  
Good

**Oil level** Good before and after oil changed

**Oil change performed (date)** 05/09/2023

**Air filter( condition)** New

**Air dryer associated with compressor (Yes or No)** Yes

**Air dryer operation** Working properly

**Clean coils** Cleaned the condenser coil



Drains/auto/ dryer/  
tank (operation)  
Notes / Issues

All clear and clean.  
Changed both oil filters and air filter today. Changed oil. Unit is running  
good at this time.




Attachments

Title

5-9-23 ECS  
Compressor PM's  
20230509\_104716  
05/09/2023 02:18 PM


File Name

5-9-23 ECS Compressor PM's.pdf  
6b6052b5-95b0-4dbe-9836-61655d48d0d1.jpg




20230509\_113142  
05/09/2023 02:18 PM

a9054905-da05-4ce7-b416-84639e3cc33b.jpg




20230509\_123021  
05/09/2023 02:18 PM

b119c47d-a549-4893-a761-748ba7490bc1.jpg




20230509\_115546  
05/09/2023 02:18 PM

1f41ef34-68ac-4b8a-bb46-1c00c5661e97.jpg




20230509\_104723  
05/09/2023 02:18 PM

fb8c377a-2632-4b37-b15d-de1c6a9ea700.jpg



20230509\_112924  
05/09/2023 02:18 PM

544aca3a-4683-49ff-9ca5-3798a7edb459.jpg



20230509\_112930  
05/09/2023 02:18 PM

0dc9711b-101c-4965-9531-83a2ee61db03.jpg



### CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: PA118 Date of Visit: 5/9/23

Contractor Personnel on Site:

1. Tom Timlin 2.

#### Work Performed:

**Preventive Maintenance** - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1.

#### Service Calls – Service Call Number and Description


1. CSS#   
2. CSS#   
3. CSS#

---

### CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Thomas Timlin Date: 5/9/23

Signed: 

To be signed by Facility Manager:

By signing the Certification of Work, I certify that the above-named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed. This is **NOT** a Certification that the Work was performed correctly – The COW simply verifies that that someone representing the Contractor was onsite and accomplished something

Print Name/Rank: Cynthia Croyle/ AFOS Date: 5/9/23

Signed: 

E-Mail: cynthia.a.croyle.ctr@army.mil