



March 2021 Annual Inspection

Prepared for:




Tidewater, Inc. Bedford, VA

919 Blue Ridge Avenue
Bedford, VA 24523

on




3/5/2021

Table of Contents




	 High	 Med	 Low	Section
Work Order	0	0	0	1.0
Inspection - <i>Utility Shop</i>	Cranes: 52564767 - N/A	0	0	2.0

Overview

Breakdown by Form

Form Type	 High	 Med	 Low	# Forms
Inspection	0	0	0	1
Work Order	0	0	0	1
Overall:	0	0	0	2

Breakdown by Location

Location	 High	 Med	 Low	# Forms
Not Specified	0	0	0	1
Utility Shop	0	0	0	1
Overall:	0	0	0	2

Breakdown by Asset

Asset Type	 High	 Med	 Low	# Assets
Cranes	0	0	0	1
Overall:	0	0	0	1



Foley Material Handling Company, Inc.
11351 Virginia Crane Dr.
Ashland, VA 23005
(855) 202-5999


Work Order

Tidewater, Inc. Bedford, VA
919 Blue Ridge Avenue
Bedford, VA 24523

Performed By: Shane Lucas
Date Completed: 03/01/2021

FolderID: 2152
FormID: 10094455

Priorities Found:

Inspection Work Order	
1. Customer Name	<i>Tidewater, Inc. - U.S. Army Reserve Center</i>
2. Address	<i>919 Blue Ridge Avenue Bedford, VA 24523</i>
3. Contact	<i>Don Huson</i>
4. Phone Number	<i>P: 540-266-4003 / C: 614-623-9569 Tina Lee</i>
5. Lift Type (if required)	<i>FMH 20' Scissors Lift</i>
6. Call Ticket #	<i>18330</i>
7. Purchase Order#	<i>Purchase order to be issued by customer at job site.</i>
8. Start Date	03/01/2021
9. Completion Date	03/01/2021
10. Information/Remarks	<i>March 2021 annual inspection of cranes and hoists.</i>
11. Special Notes	<i>Crane located in Bedford, VA at the U.S Army Reserve Center, but the customer is Tidewater, Inc. Invoice thru portal.</i>
Signatures	
12. Inspector/Technician	Shane Lucas 
13. Customer Contact	Don Huson

Foley Material Handling disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Foley Material Handling. Foley Material Handling shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.





Foley Material Handling Company, Inc.
11351 Virginia Crane Dr.
Ashland, VA 23005
(855) 202-5999

Inspection

Tidewater, Inc. Bedford, VA
919 Blue Ridge Avenue
Bedford, VA 24523

FolderID: 2152
FormID: 10094454



Cranes

Completed by: Shane Lucas on 03/01/2021

Location: Utility Shop

Equipment Number: 52564767

Crane Serial Number: N/A

Status: In Service

Type:	SGTR
Crane Manufacturer:	Cincinnati
Trolley Configuration :	Main Trolley
Hoist Configuration:	Main Hoist
Control Type:	Pendant
Rated Load:	10 Tons
Voltage:	460V-3Ph-60Hz
Main Hoist Size:	11mm
Main Hoist Construction:	Wire Rope
Main Hoist Parts:	4
Main Hoist Serial:	HMW32706
Main Hoist Manufacturer:	R&M
Main Hoist Model:	SX50410100P55FDL0F

Priorities Found: ● **61 - Good**

Inspection Type

● 1. Frequency	Annual
---	--------

Historical Records

● 2. Periodic Inspection	Satisfactory
● 3. Preventive Maintenance	Satisfactory
● 4. Load Test	Satisfactory

Runways & Supporting Structure

● 5. Foundations/Anchorages	Satisfactory
● 6. Runway/Support	Satisfactory
● 7. Runway Stops & Bumpers	Satisfactory
● 8. Runway Rails	Satisfactory
● 9. Rail Splicing	Satisfactory
● 10. Rail Attachment	Satisfactory

Bridge Components

● 11. Rated Load Markings	Satisfactory
● 12. Directional Markings	Satisfactory
● 13. Girders/Structure	Satisfactory
● 14. Bolts & Rivets	Satisfactory
● 15. Guards/Covers	Satisfactory
● 16. Gears & Gear Boxes	Satisfactory
● 17. Brakes	Satisfactory
● 18. Drive Shaft	Satisfactory

Foley Material Handling disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Foley Material Handling. Foley Material Handling shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

19.	Motors	Satisfactory
20.	End Trucks	Satisfactory
21.	Bridge Wheels	Satisfactory
22.	Bridge Bumpers	Satisfactory
23.	Rail Sweeps	Satisfactory
Main Trolley		
24.	Frame / Structure	Satisfactory
25.	Trolley Wheels	Satisfactory
26.	Safety Lugs	Satisfactory
27.	Trolley Gauge	Satisfactory
28.	Trolley Rails	Satisfactory
29.	Bumpers	Satisfactory
30.	Stops	Satisfactory
31.	Guards/Covers	Satisfactory
32.	Drive Motors	Satisfactory
33.	Brakes	Satisfactory
34.	Drive Shaft	Satisfactory
35.	Gears & Gear Boxes	Satisfactory
Main Hoist		
36.	Wire Rope Condition	Satisfactory
37.	Wire Rope Guide	Satisfactory
38.	Load Block	Satisfactory
39.	Sheaves / Pocket Wheel - Upper / Lower	Satisfactory
40.	Hook & Safety Latch	Satisfactory
41.	Rope Drum & Grooves	Satisfactory
42.	Upper Limit Switch	Satisfactory
43.	Lower Limit Switch	Satisfactory
44.	Motor Brake (Holding)	Satisfactory
45.	Load Brake (Control)	Satisfactory
46.	Hoist Motor	Satisfactory
47.	Gears & Gear Boxes	Satisfactory
Electrical Equipment		
48.	Runway Disconnect	Satisfactory
49.	Runway Conductor Bar	Satisfactory
50.	Collectors	Satisfactory
51.	Bridge/Mainline Disconnect	Satisfactory
52.	Festoon Systems (Bridge, Trolley & Pendant)	Satisfactory
53.	Control Panels (Bridge, Trolley & Hoist)	Satisfactory
54.	Resistors	Satisfactory
Pendant Controls		
55.	Buttons	Satisfactory
56.	Functions Identified	Satisfactory
57.	Enclosure	Satisfactory
58.	Pendant Cord	Satisfactory
59.	Pendant Strain Relief	Satisfactory
60.	Warning Label	Satisfactory
Miscellaneous		

Foley Material Handling disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Foley Material Handling. Foley Material Handling shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

