

**CERTIFICATION OF WORK
PREVENTIVE MAINTENANCE**

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY113 Date of Visit: 1/9/20 - 1/10/20
1/28/20

Contractor Personnel on Site:

1. Patrick Brown 3. _____
2. _____ 4. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO'S 6828PMM, WO 6838PMQ, 6846PMS, 6829PMM, 6839PMQM,
2. 6847PMS, 6847PMS, 6840PMQ, 6848PMS, 6888PMQ, 6891 PMQ
3. GATES, LIGHTING, DEHUMIDIFIER, OVERHEAD DOORS, FILTERS
4. _____
5. _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Patrick Brown Date: 1/28/20

Signed: 

To be signed by Facility Manager:


By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: MARYLD EDMUNDS Date: 1/28/20

Signed: 

E-Mail: _____

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
INTERIOR LIGHTING

ACTIVITY AND BLDG #: **NY113-01**MECHANIC
SIGNATURE: DATE: **1/9/20**

LOCATION/RM #:	WO# 6838	ASSET # 190917-539	START TIME: 10am	FINISH TIME: 10:30am
----------------	-----------------	---------------------------	-------------------------	-----------------------------

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)
		YES	NO	
TO BE PERFORMED AT EACH INSPECTION SERVICE				
1	Visually check all accessible areas for burned out bulbs and/or flickering lights. Check with the facility manager to see if they know of any outages.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	no burned bulbs or flickering
2	Replace bulbs where applicable. Note quantity of bulbs replaced. If lift is required, schedule accordingly.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	no bulbs replaced
3	Test light fixture. If light does not work, replace starters and/or ballasts as necessary.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	all lights are working
4	Note and report any needed electrical repairs.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	no electrical repairs needed
5	Properly dispose of any non-working bulbs and ballasts.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	no bulbs or ballast disposed of
6	Clean up area and remove any trash.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency.

To be performed by: General Maintenance Worker

Additional Notes: