

**CERTIFICATION OF WORK**  
(To be completed by the Contractor and saved in the Contractor's CMMS)

**INSPECTION, TESTING, AND CERTIFICATION OF WORK**  
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY030, NY070, NY126 Date of Visit: 5/10/19

Contractor Personnel on Site:

1. _____	4. _____
2. _____	5. _____
3. _____	6. _____

**Work Performed:**

**Inspection, Testing, and Certification**

1. NY030 WO 8891 Asset 6572 WO 8892 Asset 6574 WO 8893 Asset 6576
2. WO 8894 Asset 6577 WO 8895 Asset 6656
3. NY070 WO 8930 Asset 6588 WO 8931 Asset 6605
4. NY126 WO 8852 Asset 6529 WO 8853 Asset 6530

---

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: Timothy R Houk Date: 07/09/2019

Signed: Timothy R Houk

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: John F. Granata AFOS Date: 7/9/19

Signed: John F. Granata

E-Mail: john.f.granata.ctr@mail.mil



## OneCIS Insurance Company

95 Oakwood Rd  
Lake Zurich, IL 60047  
(855) 593-5115  
[www.us.bureauveritas.com](http://www.us.bureauveritas.com)

WO 8891 Asset 6572  
WO 8892 Asset 6574  
WO 8893 Asset 6576  
WO 8894 Asset 6577  
WO 8895 Asset 6656

7/2/2019

44110-007210.00

CPT ALden D Allen AFRC  
3126 Lake Rd  
Horseheads, NY 14845-3103

**RE: Jurisdictional Inspection:**  
CPT ALden D Allen AFRC  
3126 Lake Rd  
Horseheads, NY 14845-3103

Thank you for the consideration I received during my visit on May 10, 2019 at your facility listed above. The purpose of the visit was to perform the jurisdictional inspections of the objects listed below to determine compliance with jurisdictional laws and regulations. I was accompanied by John Granata Area Facility Operations Specialist, 585-944-9099, during my visit.

The inspections were performed on behalf of Tidewater, Inc. (US Army Reserve Offices).

The following objects were inspected at the time of the visit:

Year Built	Type of object	Jurisdictional Number	NB Number	Recommendation(s)
2007	Water Tube	3781	3781	None
2007	Water Tube	3780	3780	None
2007	Water Tube	3782	3782	None
2007	Water Tube	3783	3783	None

The following observations were noted during the inspection of this equipment: the boilers and the boiler room were in good working order.

As a result of these inspections 0 recommendations were suggested.

Based upon this visit, OneCIS Operating Certificates for each boiler are being created and forwarded to the client.

This document is advisory in nature. Reports or certificates provided in connection with any state-required boiler or pressure vessel inspection do not mean that all hazards or conditions were controlled at the time of the inspection. No liability is assumed by the information contained in this document.

The next inspection is tentatively scheduled to be completed by 05/10/2020.

Please contact me by phone at 724-396-5433 or by e-mail at [joseph.klages@bureauveritas.com](mailto:joseph.klages@bureauveritas.com) if there are any questions and to clear any recommendations.

Sincerely,

*Joseph Klages*

Joseph Klages  
Jurisdictional Inspection Specialist

#### DISTRIBUTION

Cc:

Tidewater Inc.  
Adam Colopy  
3761 Attucks Dr  
Powell, OH 43065-6080  
[adam.colopy@tideh2o.net](mailto:adam.colopy@tideh2o.net)