

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

INSPECTION, TESTING, AND CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: ~~NY010, NY025, NY065~~ ~~XXXX~~

Date of Visit: 5/9/19

Contractor Personnel on Site:

- | | |
|----------|----------|
| 1. _____ | 4. _____ |
| 2. _____ | 5. _____ |
| 3. _____ | 6. _____ |

Work Performed:

Inspection, Testing, and Certification

- NY010 WO 8932 Asset 6589 WO 8933 Asset 6606 WO 8934 Asset 6616
- WO 8935 Asset 6623 WO 8936 Asset 6625
- NY025 WO 8922 Asset 6585 WO 8923 Asset 6602
- ~~NY065 WO 8980 Asset 6556 WO 8981 Asset 6557~~

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Timothy R Houk Date: 07/09/2019

Signed: *Timothy R Houk*

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: CRYSTAL RECORDS Date: 9 JUL 19

Signed: Crystal L. Records
Digitally signed by Crystal L. Records
Date: 2019.07.09 13:16:23 -04'00'

E-Mail:

CRYSTAL.L.RECORDS.CTR@MAIL.MIL



OneCIS Insurance Company

95 Oakwood Rd
Lake Zurich, IL 60047
(855) 593-5115
www.us.bureauveritas.com

WO 8932 Asset 6589
WO 8933 Asset 6606
WO 8934 Asset 6616
WO 8935 Asset 6623
WO 8936 Asset 6625

7/2/2019

44110-007210.00

Amherst USARC
100 N Forest Rd
Buffalo, NY 14221-5244

RE: Jurisdictional Inspection:
Amherst USARC
100 N Forest Rd
Buffalo, NY 14221-5244

Thank you for the consideration I received during my visit on May 9, 2019 at your facility listed above. The purpose of the visit was to perform the jurisdictional inspections of the objects listed below to determine compliance with jurisdictional laws and regulations. I was accompanied by Crystal Records Area Facility Operation Specialist, 716-275-431, during my visit.

The inspections were performed on behalf of Tidewater, Inc. (US Army Reserve Offices).

The following objects were inspected at the time of the visit:

Year Built	Type of object	Jurisdictional Number	NB Number	Recommendation(s)
2010	Water Tube	165943	165943	None
2010	Water Tube	165932	165932	None
2010	Water Tube	164958	164958	None
2010	Water Tube	165928	165928	None
2010	Water Tube	165940	165940	None

The following observations were noted during the inspection of this equipment: the boilers and the boiler room were in good working order.

As a result of these inspections 0 recommendations were suggested.

Based upon this visit, OneCIS Operating Certificates for each boiler are being created and forwarded to the client.

The next inspection is tentatively scheduled to be completed by 05/09/2020.

Please contact me by phone at 724-396-5433 or by e-mail at joseph.klages@bureauveritas.com if there are any questions and to clear any recommendations.

Sincerely,

Joseph Klages

Joseph Klages
Jurisdictional Inspection Specialist

DISTRIBUTION

Cc:

Tidewater Inc.
Adam Colopy
3761 Attucks Dr
Powell, OH 43065-6080
adam.colopy@tideh2o.net