

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
VEHICLE EXHAUST REMOVAL

SITE AND BLDG #: WV035-02

**MECHANIC
SIGNATURE:**

Andy Bird DATE: 12-13-11

LOCATION/RM #:

START TIME: 7:30 AM


FINISH TIME: 3PM

Site Location	WO #	Asset #	PM #	Manufacturer	Model Number	Serial #	Asset Description	Asset Location
WV035-02	6616	8073	PM-QT-8073		N/A	N/A	J-1502000-57 2-pc Overhead Vehicle Exhaust System	AMSA Shop
WV035-02	6616	8091	PM-QT-8073	N/A	N/A	N/A	J-1502000-57 Vehicle Exhaust System	AMSA Shop

CHECK POINT	CHECKPOINT DESCRIPTION	TASK COMPLETE		NOTES/ ACTIONS (IF TASK COMPLETE IS CHECKED NO, PROVIDE EXPLANATION)	
		YES	NO	SPECIAL INSTRUCTIONS	
TO BE PERFORMED AT EACH INSPECTION SERVICE					
1	Start and stop fan with local switch				
2	Check motor and fan shaft bearings for noise, vibration, overheating; lubricate bearings.				
3	Inspect, adjust belts and pulleys. Replace belt as needed.				
4	Clean dampers; lubricate pivot points (annually) and inspect linkages for tightness.				
5	Inspect fan for bent blades, unbalance, excessive noise, and vibration.				

7	Visually inspect exhaust system tubing and/or duct work for any damage that could result in leaks.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8	Repair as needed	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**



Hose Reels not functioning.
Will not reel back up.
Hoses and Reels need replaced!
CM Needed

