

S

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: WV032

Date of Visit: 07/22/19

Contractor Personnel on Site:

1. Hunter Alderman

2. Behnam Gholian

Work Performed:

- Combo change on vault motion sensor
- TDS check results - Success/passed

Recommend to change X07 on vault currently to S/6 2937 99th

Please take pictures

---

CERTIFICATION OF WORK

To be signed by the Tech:

Print Name: Hunter Alderman Date: 07/22/19

Signed: Hunter Alderman

To be signed Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name: Paul Crouse Date: 07/22/19

Signed: Paul Crouse

E-Mail: Paul.E.Crouse.Civ@mail.mil