

Date: 3-15-24

Region: 4C

CSS No.: 89878

FAC ID: WV002

Maximo WO No.: 13988

Asset #:

Priority: 2



**Original Work Request:**

Watts Regulator 300 psi, 2" pressure release valve is not holding pressure on the main water line, needs replacing.

**Description of Repairs Needed:**

Labor and materials to replace the 2" pressure reducing valve on the main water line that is not holding pressure.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	11	\$ 116.10	\$ 1,277.10
			\$ -

**Material List:**

	Quantity	Cost	Total
2" pressure regulator (model #25AUB)	1	\$ 1,038.23	\$ 1,038.23
Misc (1 pressure union, 2" copper pipe, 2 copper fittings and consumables)	1	\$ 255.41	\$ 255.41
Trip Charge	1	\$ 110.00	\$ 110.00
			\$ -
			\$ -
			\$ -
			\$ -

**Equipment List:**

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

**PM WO History:**



**Estimate Summary:**

Labor	Material	Equipment
\$1,277.10	\$1,403.64	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,680.74	\$321.69	\$160.84	\$3,163.27