

Date: 8-06-24

Region: 4C

CSS No.: 94603

FAC ID: WV002

Maximo WO No.: 16383

Asset #:

Priority: 2



Original Work Request:

OMS 2 air handler need repaired or replaced.

Description of Repairs Needed:

Investigation is to troubleshoot the power supply OMS-2AHU. Suspected broken neutral feeding unit and possible L1 Voltage drop. Note: Not to exceed (10) hours of labor. Customer will only be invoiced for the labor hours used. Once repairs are identified, a separate quote will follow.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	10	\$ 138.00	\$ 1,380.00
Trip Charge	20	\$ 1.75	\$ 35.00

Material List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

Equipment List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,415.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,415.00	\$169.80	\$84.90	\$1,669.70