

Date: 4-9-26



Region: 4C

FEMS/CSS No.: 2965840

FAC ID: WV002

Maximo WO No.: 21673

Asset #:

Priority: 3

Original Work Request:

Soldier broke the door in because his key wouldn't work, later discovered his key was for a different door. Vendor should verify all measurements for door and existing frame. Recycled from old door is door closure and both kickplates. Recommended contractor: Appalachian Lock for hardware

Description of Repairs Needed:

Proposal is for supplier price increase on materials. Project is to remove existing damaged door and hardware. Retain door closure, window, kick plates and hinges to be reused. F&I new 85.5" x 36" solid birch door with approved finish. Install window, kick plates, door closure and hinges from existing door. F&I new lever handle compatible with existing core. Dispose of old door offsite

Labor:

	Labor Hrs	Labor Rate	Total
			\$ -
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
Door with finish	1	\$ 300.00	\$ 300.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$0.00	\$300.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$300.00	\$36.00	\$18.00	\$354.00