

Date: 3-6-26



Region: 4C

FEMS/CSS No.: 3366061

FAC ID: WV005

Maximo WO No.: 21478

Asset #:

Priority: 2

Original Work Request:

Batteries for the IDS Panel inside the vault need replacing, they are expired (dated 2016) these need to be 12v, 7 ah batteries.

Description of Repairs Needed:

Replace batteries in IDS panel inside vault

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	150	\$ 8.00	\$ 1,200.00
CC payment surcharge	1	\$ 52.00	\$ 52.00
			\$ -

Material List:

	Quantity	Cost	Total
12 vdc and 7 ah batteries	2	\$ 50.00	\$ 100.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,252.00	\$100.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,352.00	\$162.24	\$81.12	\$1,595.36