

Date: 8/29/2023

Region: 4C
FAC ID: WV006

CSS No.: 93731
Maximo WO No.: 13365

Asset #:

Priority: 3



Original Work Request:

The water fountain on 1st floor outside mens and womens locker room is clogged and needs repaired.

Description of Repairs Needed:

Initial response by CMI Tech (unable to unclog drain, believed clog to far for equipment). Contacted plumber to unclog.

Labor:

	Labor Hrs	Labor Rate	Total
1 Tech	3	\$ 89.50	\$ 268.50
			\$ -

Material List:

	Quantity	Cost	Total
Drill/Equipment (Eel) to Unclog Drain	1	\$ 35.00	\$ 35.00
Truck & Consumables	1	\$ 34.11	\$ 34.11
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$268.50	\$69.11	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$337.61	\$40.51	\$20.26	\$398.38