

Date: 8/30/2023

Region: 4C

FAC ID: WV006

CSS No.: 94512

Maximo WO No.: 13628

Asset #:

Priority: 2



Original Work Request:

Replace fill valve solenoid on ice machine in kitchen

Description of Repairs Needed:

Order and replace fill valve assembly on Scottsman Ice Machine

Labor:	Labor Hrs	Labor Rate	Total
1 Tech	2	\$ 100.00	\$ 200.00
			\$ -

Material List:	Quantity	Cost	Total
Fill Valve Assembly S-45, 1.4 GPM 120VAC	1	\$ 143.25	\$ 143.25
(FW10570001100)			\$ -
Shipping/Handling	1	\$ 30.00	\$ 30.00
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$200.00	\$173.25	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$373.25	\$44.79	\$22.40	\$440.44