

Date: 12-14-23

Region: 4C  
FAC ID: WV006

CSS No.: 96117  
Maximo WO No.: 14555

Asset #:

Priority: 1



**Original Work Request:**

Glycol leak: Casto was at this facility and performed pMs on the boilers on Nov 28, 2023, at that time the glycol feeder was empty. After 10 days we have gone thru 20 gal of glycol. Cmi has a quote from Casto to find the leak. This needs to be done so the facility won't go without heat and we need to stop the leak of glycol. We have walked thru facility and can't find any leaks around any of the equipment or ceiling tile. Recommended Contractor: Casto

**Description of Repairs Needed:**

Investment is NTE labor to locate and if possible, repair the glycol leak on the boiler. NOTE 1: Customer will only be invoiced for the labor hours used. NOTE 2: If parts or additional labor is needed to complete the repair, a separate quote will be submitted.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (2) Not To Exceed Quote (labor only)	1	\$ 3,238.00	\$ 3,238.00
			\$ -

**Material List:**

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**Equipment List:**

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$3,238.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$3,238.00	\$388.56	\$194.28	\$3,820.84