

Date: 6-17-24

Region: 4C

FAC ID: WV006

CSS No.: 98241

Maximo WO No.: 15865

Asset #:

Priority: 1



Original Work Request:

The air compressors at the AMSA facility are not running and the unit can't use any of the pneumatic tools. This is a major issue as they cannot perform maintenance orders on the heavy equipment.

Description of Repairs Needed:

Investigated to troubleshoot issues. Discovered several wires were disconnected...stripped wires and reconnected to place system back in service. Stayed on site to ensure system was operating correctly, packed up and signed out.

Labor:	Labor Hrs	Labor Rate	Total
Tech (1)	3.5	\$ 100.00	\$ 350.00
			\$ -

Material List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$350.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$350.00	\$42.00	\$21.00	\$413.00