

Date: 6-23-25

Region: 4C

FAC ID: WV006

FEMS/CSS No.: 3189925

Maximo WO No.: 19508

Asset #:

Priority:  2



**Original Work Request:**

Hazardous material storage building roof needs repairing after storm damage.

**Description of Repairs Needed:**

Proposal is to repair roof of hazardous materials storage building. Scrap and clean loose debris from roof and recoat entire roof with Truco rubber roof coating. Let dry and make second application

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	8	\$ 86.75	\$ 694.02
			\$ -
			\$ -

**Material List:**

	Quantity	Cost	Total
Truco Coating (gal)	2.5	\$ 75.00	\$ 187.50
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

**Equipment List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$694.02	\$187.50	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$881.52	\$105.78	\$52.89	\$1,040.19