

Date: 2-5-2025

Region: 4C

FEMS/CSS No.: 3031076

FAC ID: WV007

Maximo WO No.: 17985

Asset #:

Priority: 1



Original Work Request:

No hot water, we have no hot water in the facility after looking at things, think it may be the circulating pump needing replaced. This is an emergency ticket.

Description of Repairs Needed:

Investigate and replace circulator pump to HW system.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	4.5	\$ 100.00	\$ 450.00
		\$	-
		\$	-

Material List:

	Quantity	Cost	Total
B&G 5Circulating Pump (1BL013LF)	1	\$ 1,217.50	\$ 1,217.50
B&G 3/4" Flange (101501lf)	1	\$ 69.99	\$ 69.99
Freight	1	\$ 50.00	\$ 50.00
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$450.00	\$1,337.49	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,787.49	\$214.50	\$107.25	\$2,109.24