

Date: 6-10-25

Region: 4C

FEMS/CSS No.: 3190184

FAC ID: WV007

Maximo WO No.: 19212

Asset #:

Priority: 1



Original Work Request:

The right front door on the facility has a Mag Lock that is not holding the door shut and the building is not secure. Need to have this repaired ASAP to keep facility secure.

Description of Repairs Needed:

Trouble shot Mag Lock and adjusted door closer and plate on Mag Lock. Mag Lock appeared to work properly as door closed and timed out as designed.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1) (labor/travel)	2	\$ 148.00	\$ 296.00
fuel surcharge	1	\$ 59.90	\$ 59.90
			\$ -

Material List:

	Quantity	Cost	Total
shop supplies (lubricants, rags, etc.)	1	\$ 29.65	\$ 29.65
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$355.90	\$29.65	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$385.55	\$46.27	\$23.13	\$454.95