

Date: 9-10-25

Region: 4C

FAC ID: WV007

FEMS/CSS No.: 3313741

Maximo WO No.: 20083

Asset #:

Priority: 1



Original Work Request:

Repair shower valve, the men's shower on first floor will not shut off and when we tried to shut off behind the handle, we had no luck, so we had to shut water off to the first floor men's restroom and the lactation room. The shower valve will need to be replaced. POC Mr. Modock (440) 309-6527

Description of Repairs Needed:

Proposal is to cut and remove existing non functional shower valve in the men's shower room and replace with a new delta single handle shower valve

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	24	\$ 133.33	\$ 3,200.00
			\$ -
			\$ -

Material List:

	Quantity	Cost	Total
delta single handle shower valve (T17238)	1	\$ 275.00	\$ 275.00
tile, grout, adhesives, etc	1	\$ 100.00	\$ 100.00
miscellaneous and shop supplies	1	\$ 100.00	\$ 100.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
Hammer drill	1	\$ 167.00	\$ 167.00
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$3,200.00	\$475.00	\$167.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$3,842.00	\$461.04	\$230.52	\$4,533.56