

Additional Funding Request

Site: WV009	WO#5800 CSS # 15205 Asset# NA
Description of Repairs	Exhaust Fan INOP
Diagnosis: Initial Work Order CSS# 15205	Exhaust Fan INOP
Explanation of Additional Costs for Repairs	Labor and material to replace motor
Additional Labor Cost to Perform Repairs	Mechanic- \$115 x 5= \$575.00 Apprentice- \$93 x 5= \$465.00
Additional Material Cost to Perform Repairs	\$279.84
Total Cost of Repair	\$1,319.84



QUOTE

Client Name: USARC - Clarksburg WV00

Contact: Jennifer Bailie

Date: 02/27/2019

Quote Number: 156812

Location: USARC - Clarksburg WV009

6 Armory Road

AMSA #102 (G)

Clarksburg, WV 25301

PO Box 627
540 Leon Sullivan Way
Charleston, WV 25301
Charlie Cook
304-346-0549x1252
304-346-8920 Fax
service@castotech.com

<i>Description</i>	<i>Quantity</i>	<i>Price</i>	<i>Line Total</i>
GF2034 Motor, United Refrig	1.00	\$132.36	\$132.36
3L320 Belt, United Refrig	1.00	\$10.48	\$10.48
Shipping & Handling	1.00	\$52.00	\$52.00
Onsite Labor Mechanic	5.00	\$115.00	\$575.00
Onsite Labor Apprentice	5.00	\$93.00	\$465.00
Trip Charge	20.00	\$1.75	\$35.00
Miscellaneous Parts	1.00	\$50.00	\$50.00
Subtotal:			\$1,319.84
Estimated Sales Tax:			\$0.00
Total:			\$1,319.84

Investment is labor and materials to replace the exhaust fan motor and fan belt for the first floor restroom, EF-9, located at USARC Clarksburg, WV009, CSS# 15205.

This is a quotation on the goods named and further subject to the standard terms and conditions attached hereto.

Acceptance of quotation

Authorized Representative

Purchase Order #

☐ Warranty Option – For an additional \$65.99, I'd like to extend the labor warranty to 12 months.

EXCLUSIONS:

1. All asbestos testing and removal will be owner's responsibility
2. All roof work

CLARIFICATIONS:

1. The price of a performance/payment bond is not included.
2. The cost of permits and inspections by outside authorities are not included.
3. Work will be performed during normal business hours (**Monday-Friday, 8:00 a.m.-4:30 p.m.**).
4. Our terms are net thirty days.
5. Price held firm for 60 days.
6. Standard Warranty - 1 year parts and 90 days labor.

***Thank you for your
business!***

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: wv009 Date of Visit: 12/3/2018

Contractor Personnel on Site:

1. Robert Gifford
2. Carter Householder

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO# 153351

Service Calls – Service Call Number and Description

1. CSS# 15205
2. CSS# _____
3. CSS# _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Robert Gifford Date: 12/3/2018

Signed: 

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Karen Hill GS07 Date: 12/3/2018

Signed: 

E-Mail: karen.y.hill2.civ@mail.mil

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: wv009 Date of Visit: 12/3/2018

Contractor Personnel on Site:

1. Robert Gifford
2. Carter Householder

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO# 153351

Service Calls – Service Call Number and Description

1. CSS# 15205
2. CSS# _____
3. CSS# _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Robert Gifford Date: 12/3/2018

Signed: 

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Karen Hill GS07 Date: 12/3/2018

Signed: 

E-Mail: karen.y.hill2.civ@mail.mil

CentriMaster®

Model : PNN135F 115/1/60/ODP 1725 1637
RPM

Set No : UUF630316

Amps : 1

Volts : 115

Hp : .330

Hz : 60 Ph : 1

Tag : EF-8



ACME ENGINEERING & MANUFACTURING CORP.
MUSKOGEE, OKLAHOMA, USA

CAUTION/ATTENTION


THIS UNIT HAS ROTATING PARTS
AND SAFETY PRECAUTIONS SHOULD
BE EXERCISED DURING INSTALLA-
TION, OPERATION + MAINTENANCE.
GUARDS MUST BE INSTALLED WHERE
FAN IS WITHIN REACH OF PEOPLE
OR WITHIN 2.5 METERS OF WORK-
ING LEVEL OR WHEN DEEPER CON-
SIDERED NECESSARY.

INSTALLER AVEC LES PARTIES
MOBILES INFERIEURES AU NIVEAU
A 2.5 METERS AU-DESSUS DU
NIVEAU DU PLANCHER OU DU SOL

DE

ERICA

Order #	66892961-00
Terms	1% 10th prox, Net 30 prox
Customer P/O	

Bill To: 1022239
CASTO-TECHNICAL SERVICES INC
WHEELING ACCOUNT Y4
PO BOX 627
Charleston, WV 25322


Ship To
CASTO-TECHNICAL SERVICES INC
WHEELING ACCOUNT Y4
PO BOX 627
Charleston, WV 25322

Branch:
United Refrigeration Inc.
340 Third Ave.
SOUTH CHARLESTON, WV 25303
(304)344-3681 FAX#: (304)344-4826
branchY5@uri.com

Cust#: 1022239	Order Date: 02/27/19	Whse: 0Y5	Taken By: TMB	Sales out: Y52
----------------	----------------------	-----------	---------------	----------------

Special Instructions:

Ref:

Product Ln# And Description	Quantity Ordered	Quantity B.O.	Quantity Shipped	Qty. UM	Unit Price	Amount (Net)
1 GF2034 CENTURY 1/3HP 1725RPM 115V 48fr/56 SP 4P MOTOR	1			ea	110.30	110.30
2 3L320-B BROWNING V-BELT 3/8 W X 32 L OD FHP	1			ea	8.73	8.73

2 Lines Total					Total	119.03
					Invoice Total	119.03

**** NOT AN INVOICE OR RECEIPT ****

**** This Quote Will Expire On: 03/29/19 ****