

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: WV016 Date of Visit: 3/14/19

Contractor Personnel on Site:

1. Jesse Biddle 2. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO# 155247

Service Calls - Service Call Number and Description

1. CSS# 16385
2. CSS# _____
3. CSS# _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Jesse Biddle Date: 3/14/19

Signed: Jesse Biddle

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Ritchie, Eric B. Date: 20190314

Signed: E. B. Ritchie

E-Mail: eric.b.ritchie.str@mail.mil

NO FTS onsite

SERVICE REPORT

CUSTOMER P.O. NO. _____

SERVICE REQUESTED CSS#16385

Refrigerant Removed:	Qty	lb	oz	TYPE
----------------------	-----	----	----	------

Total Charge:

WORK PERFORMED/UNIT INFO.

I changed the pump and aquastat and blown fuse. Was able to install and setup everything, but couldn't test due to no water at the building.

NATURE OF WORK

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

SUMMARY OF TIME

[illegible]

JOB COMPLETE YES X NO _____ EXPLAIN _____

SIGNATURE _____
Customer Representative

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 3/14/19 ARRIVAL TIME 1:00PM DEPARTURE TIME 6:06PM JOB/TCK. NO. 156780

CUSTOMER P.O. NO. _____

JOB NAME/LOCATION Camden ClarkSERVICE REQUESTED Bad Condenser fan on winter chiller

Manufacture: _____				
Model#: _____				
Serial#: _____				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested☐ Leak Found☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

I changed out bad fan motor and tested its operation.
Everything ran fine.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service ☒ _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR	

SUMMARY OF TIME

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER
Jesse Biddle	1.5				1.5					

JOB COMPLETE YES ☒ NO _____ EXPLAIN _____

SIGNATURE _____

Customer Representative

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 3/14/19 ARRIVAL TIME 1:00PM DEPARTURE TIME 6:00PM JOB/TCK. NO. 157064

CUSTOMER P.O. NO. _____

JOB NAME/LOCATION Camden ClarkSERVICE REQUESTED AHU2A Duct Static Issue☐ Leak Tested☐ Leak Found☐ Leak Repaired

Method: _____

Total Charge: _____

Manufacture: _____

Model#: _____

Serial#: _____

Refrigerant Added: Qty lb oz TYPE

Refrigerant Removed: Qty lb oz TYPE

WORK PERFORMED/UNIT INFO. _____

I looked into issue and found the transducer fine.
I checked the tubing through the AHU and found
a bad spot in the tubing. I patched the tube and will
fix permanently tomorrow.

NATURE OF WORK

Regular Service ☒

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR	

SUMMARY OF TIME

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER
<u>Jesse Biddle</u>	<u>3.5</u>				<u>3.5</u>					

JOB COMPLETE YES _____ NO X EXPLAIN _____

SIGNATURE _____

Customer Representative