



## OneCIS Insurance Company

95 Oakwood Rd  
Lake Zurich, IL 60047  
(855) 593-5115  
[www.us.bureauveritas.com](http://www.us.bureauveritas.com)

BUREAU  
VERITAS

9/4/2019

44110-007211.00

International Support Group  
RR 1 Box 174  
Big Bend, WV 26136-9724

**RE: Jurisdictional Inspection:**  
International Support Group  
RR 1 Box 174  
Big Bend, WV 26136-9724

Thank you for the consideration I received during my visit on August 21, 2019 at your facility listed above. The purpose of the visit was to perform the jurisdictional inspections of the objects listed below to determine compliance with ASME/National Board standards and regulations. I was accompanied by Eric Ritchie during my visit.

The inspections were performed on behalf of International Support Group (US Army Reserve Offices).

The following objects were inspected at the time of the visit:

Year Built	Type of object	Jurisdictional Number	NB Number	Recommendation(s)
	Water Tube	WV016-BLR1	1796	None
2004	Water Tube	WV016-BLR2	13053	None
1997	Water Tube	WV016-002	5179	None

The following observations were noted during the inspection of this equipment:

**WV016-002:** Boiler was inspected externally and found free of damage or defect. Required safety devices are present and appear to be in good working order. Pressure relief valve was tested and found satisfactory.

**WV016-BLR1 and WV016-BLR2:** Boilers are out of service owing to damage to the electrical supply to the boiler room occasioned by water damage/burst pipes from past winter. Boilers themselves appear free of damage with required safety devices present. It is recommended that controls/safety devices be tested immediately upon returning the boiler to service.

This document is advisory in nature. Reports or certificates provided in connection with any state-required boiler or pressure vessel inspection do not mean that all hazards or conditions were controlled at the time of the inspection. No liability is assumed by the information contained in this document.

As a result of these inspections 0 new recommendations were suggested.

Based upon this visit and the results of the National Board Inspection Code (**NBIC**) inspection requirements, OneCIS Operating Certificates for each boiler are being created and forwarded to the client.

The next inspection is tentatively scheduled to be completed by 08/21/2020.

Please contact me by phone at 571-373-0998 or by e-mail at [wiliam.johnson@onecis.com](mailto:wiliam.johnson@onecis.com) if there are any questions or if I may be of further assistance.

Sincerely,

*William Garth Johnson*

William Garth Johnson  
B&M Jurisdictional Specialist

#### DISTRIBUTION

Cc:

International Support Group  
Jamie Merchant  
9050 Pines Blvd Ste 150  
Pembroke Pines, FL 33024-6400  
[jmerchant@internationalsupportgroup.com](mailto:jmerchant@internationalsupportgroup.com)