

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: WVO20 Date of Visit: 16AUG19

Contractor Personnel on Site:

1. GEORGE GRANT 2. ANDY BIRD

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO# 6422

Service Calls - Service Call Number and Description

1. CSS# 15990
2. CSS# _____
3. CSS# RE-PIPE BOILER PRV'S

Pictures are required (Before and After)

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: GEORGE E. GRANT Date: 16AUG19
Signed: GEORGE E. GRANT

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Lahomma Fowler Date: 16 Aug 19
Signed: Lahomma Fowler
E-Mail: lahomma.ol.fowler.civ@mail.mil



3

THIS EQUIPMENT IS EQUIPPED WITH A
MANUAL SHUT-OFF SYSTEM AUTOMATICALLY ACTUATED BY
HIGH-TEMPERATURE SENSORS. IF
THIS EQUIPMENT HAS TO BE OPERATED DURING
THESE CONDITIONS, THE MANUFACTURER RECOMMENDS THAT
THE EQUIPMENT BE OPERATED BY A QUALIFIED
PERSON. THE MANUFACTURER SHOULD BE CONTACTED
FOR INSTRUCTIONS.

1. TURN MAIN SWITCH TO 'OFF' POSITION.

2. TURN LOW HEATER CONTROL TO GAS SHUT-OFF POSITION.

3. RESET BY PUSHING THE SMALL (RED) PLATE ON THE
MAIN SWITCH. TURN ON THE TANK POSITION AND TURN
QUASTAT TO 'ON' POSITION.

DATE

