

Date:

Region:

FEMS/CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



**Original Work Request:**

BMA faucet in the work bay has gone bad and needs replacing, it is constantly dripping and the gasket area to tighten has been stripped.

**Description of Repairs Needed:**

Replace faucet

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	2	\$ 100.00	\$ 200.00
			\$ -
			\$ -

**Material List:**

	Quantity	Cost	Total
Krowne 16-127 royal series service faucet	1	\$ 275.00	\$ 275.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

**Equipment List:**

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$200.00	\$275.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$475.00	\$57.00	\$28.50	\$560.50