

Date: 1-17-25

Region: 4C

FAC ID: WV035

FEMS/CSS No.: 2992579

Maximo WO No.: 17922

Asset #:

Priority: 1



**Original Work Request:**

FTS reported this morning, that this less than 2-yr old PTAC wall unit is clunking like a jack hammer and not working producing any heat. Is there any warranty on this piece of equipment?

**Description of Repairs Needed:**

Proposal to troubleshoot PTAC unit that's making loud noises. The PTAC is no longer under warranty and warranty documents were forwarded to COR/RFOS.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (1)	8	\$ 138.00	\$ 1,104.00
Trip Charge	40	\$ 1.75	\$ 70.00
			\$ -

**Material List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

**Equipment List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$1,174.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,174.00	\$140.88	\$70.44	\$1,385.32