

CMI Management
 Bowie Army Reserve Center
 4600 Foxtail Place
 White Plains MD 20695
 (202) 437-5119

Report Number: 328098

 Recorded By: James Harris
 (410) 991-7190
 jharris@bondwater.com

4600 Foxtail Place - HVAC

Test	Makeup Water	Cooling Tower	Dual Temp Glycol System	
Conductivity (as mmhos)	250 Record	710 400 - 1000	4600 5000 max	
pH	8.5 Record	9.0 8 - 9	9.1 8 - 10.5	
Hardness, total (ppm as CaCO ₃)	10 Record	50 400 max		
Alkalinity, total (ppm as CaCO ₃)	150 Record	400 600 max		
Chlorides	10 Record	20 200 max		
Bond EcoTrace		89 70 - 130		
Molybdate (ppm as Mo)			75 50 - 200	

Opening Comment

I met Patrick onsite to perform regular service for July. Patrick informed me that there may not be an August service.

Makeup Water



Makeup water is analyzed in order to determine cycles of concentration and to set program control parameters.

Cooling Tower



Chemical analysis found all levels within desired ranges indicating good protection against scale formation by the chemical treatment. Reviewed controller programming, ensured pumps were primed and filled chemical tanks as needed.

Dual Temp Glycol System



Testing found all levels within desired ranges indicating good corrosion protection by the chemical treatment at this time. The filter on the closed loop was replaced during this service visit.

Closing Comment

Attached with this report is the CoM for this visit. Please contact me with any questions or concerns regarding the treatment program.